



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Supervisor DDH

Minerals Regulatory Program

Date of Report: May 4, 2007

Mine Name: Hebe
Operator Name: Georgia Pacific

Permit number: M0150072
Inspection Date: April 11, 2007
Time: 3:10-3:30 PM

Inspector(s): Paul Baker
Other Participants: None
Mine Status: Inactive

Weather: Mostly cloudy, 40s

Elements of Inspection

	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

10. Revegetation

The operator transplanted several individuals of Wright fishhook cactus to an area south of the entrance. The report for the last inspection indicated most of these plants appeared to be dead, and during the current inspection, I was not able to find any live plants.

12. Other

I could not tell that there had been any recent activity at the mine. Various views of the site are in Photos 1 through 4. Photos 1 and 3 and Photos 2 and 4 make panoramas.


A truck with a horse trailer was parked at the site.

Conclusions and Recommendations:

I recommend that, if possible, a BLM botanist visit the site this spring and look for Wright fishhook cactus plants.

If the operator is not going to mine this site, it should be reclaimed. According to annual reports, the mine was last active in 2002.

Inspector's Signature



Date:



PBB:pb

cc: Georgia Pacific
Rebecca Doolittle, Price BLM

Attachment: Photos

E:\M0150072-Hebe\draft\ins-04112007.doc

ATTACHMENT

Photographs

M0150072, Hebe Mine, Georgia Pacific

Inspection Dated: April 11, 2007; Report Dated: May 4, 2007




Photo 1. This and Photos 2 through 4 show overviews of parts of the mine. Photos 1 and 3 and Photos 2 and 4 make panoramas.



Photo 2.




Photo 3.



Photo 4.